

Permit Inspections

Scheduled Date: 10/21/2026

David Stezaker

Scheduled Date	Permit Number	Inspection	Reason	Site Address	Project Description
10/21/2026	B26-00499	FOOTING	REQUESTED	828 BROCKWAY RD, ADNA	Install an in-ground pool
10/21/2026	B26-00531	FINAL INSPECTION	REQUESTED	127 MAUERMAN RD N, PE ELL	Storage and office space
10/21/2026	B26-00086	DRYWALL	REQUESTED	150 BEVILLE RD, CHEHALIS	Build a new construction single family home
10/21/2026	B26-00331	FINAL INSPECTION	REINSPECTION	356 NELSON RD, WINLOCK	Single Family Residence
10/21/2026	B26-00855	POST HOLE	REINSPECTION	1319 12 WINLOCK VADER RD, WINLOCK	Shop - Pole Building for Storage
10/21/2026	MH26-00011	FINAL INSPECTION	REQUESTED	658 FROST RD, TOLEDO	Placement of manufactured home

David Stezaker total inspection count: 6. Number of address locations: 6

Permit Inspections

Scheduled Date: 10/21/2026

Neal Bahrt

Scheduled Date	Permit Number	Inspection	Reason	Site Address	Project Description
10/21/2026	B26-00185	FRAMING COMBO	REQUESTED	471 GORE RD, ONALASKA	Relocate current teacher's quarters to new structure
10/21/2026	B26-00363	EXTERIOR SHEAR NAIL	REQUESTED	235 TWINFLOWER LN, ONALASKA	Single Family Residence
10/21/2026	B26-00363	EXTERIOR HOLD DOWN	REQUESTED	235 TWINFLOWER LN, ONALASKA	Single Family Residence
10/21/2026	B20-00904	FRAMING	REQUESTED	249 SMOKEY RIDGE RD, ONALASKA	BARN - 38x30
10/21/2026	MH20-00033	FINAL INSPECTION	REQUESTED	1408 STATE ROUTE 122, MOSSYROCK	ADU - MH Placement
10/21/2026	B20-00274	FINAL INSPECTION	REQUESTED	1408 STATE ROUTE 122, MOSSYROCK	Single Family Residence
10/21/2026	B26-00734	FOUNDATION	REQUESTED	103 BELFAIR CT, PACKWOOD	Multi-purpose cabin retreat for our family.
10/21/2026	B25-00814	FOUNDATION	REQUESTED	122 BUGLE LN, PACKWOOD	Single Family Residence
10/21/2026	B26-00212	UNDERFLOOR FRAMING	REQUESTED	145 HAYNES AVE S, PACKWOOD	SFR 3 bedroom 2 bathroom
10/21/2026	B26-00655	POST HOLE	REQUESTED	277 7TH ST, MORTON	Add a shade cover onto the end of the existing structure to provide shade and rain protection for truck loading and unloading area
10/21/2026	B26-00943	FOOTING	REQUESTED	340 CHERRY LN, MORTON	17x48 patio back of house
10/21/2026	B26-00512	FRAMING COMBO	REINSPECTION	160 FISH HATCHERY RD, MOSSYROCK	Garage - 40x48

Neal Bahrt total inspection count: 12. Number of address locations: 10